

Notification of Hazardous Waste Site

United States
Environmental Protection
Agency
Washington DC 20460

This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

D.2

810608 MI #203

MIS-000-001-175

A Person Required to Notify:

Enter the name and address of the person or organization required to notify.

Name Pennwalt Corporation - Wyandotte Plant
Street 4655 Biddle Avenue
City Wyandotte State MI Zip Code 48192

B Site Location:

Enter the common name (if known) and actual location of the site.

Name of Site Pennwalt Corporation - Wyandotte PLANT
Street 4655 Biddle Avenue
City Wyandotte County Wayne State MI Zip Code 48192

C Person to Contact:

Enter the name, title (if applicable), and business telephone number of the person contact regarding information submitted on this form.

Name (Last, First and Title) Heineman, Robert - Mgr. Energy & Environmental
Phone (313) 285-9200, ext. 365

D Dates of Waste Handling:

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1904 To (Year) 1978

US EPA RECORDS CENTER REGION 5



402896

E Waste Type: Choose the option you prefer to complete

Option 1: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

General Type of Waste:

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

1. ☒ Organics
2. ☒ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☒ Unknown
11. ☐ Other (Specify)

Source of Waste:

Place an X in the appropriate boxes.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☒ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

Specific Type of Waste:

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

000198 JUN -8 81

JUN 12 1981

F Waste Quantity: Place an X in the appropriate boxes to indicate the facility types found at the site. In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons. In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.	Facility Type 1. <input type="checkbox"/> Piles 2. <input type="checkbox"/> Land Treatment 3. <input checked="" type="checkbox"/> Landfill 4. <input type="checkbox"/> Tanks 5. <input checked="" type="checkbox"/> Impoundment 6. <input type="checkbox"/> Underground Injection 7. <input type="checkbox"/> Drums, Above Ground 8. <input checked="" type="checkbox"/> Drums, Below Ground 9. <input type="checkbox"/> Other (Specify) _____	Total Facility Waste Amount cubic feet 350,000 <input checked="" type="checkbox"/> gallons _____ Total Facility Area square feet 70,000 <input checked="" type="checkbox"/> acres _____
--	--	--

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None

not known

Note: Items Hand I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

This site contains chemical manufacturing facilities, both inorganic (begun 1898) and organic (begun 1932). It is located within the city boundaries of Riverview and Wyandotte, Michigan. The site is bounded by other industry on the North and South, the Detroit River on the East and by a Railroad and Util right-of-way and Pennwalt non-contiguous property on the West. No water wells are known to exist in the vicinity.

The bulk of wastes covered by this notification are not considered hazardous by RCRA criteria to the best of our knowledge. No hazardous wastes are currently disposed of on this site.

This location has currently on-site an active storage facility for PCB items. This storage area of approximately 600 sq. ft. currently contains some 700 gallons of PCB liquid. Design and construction of this storage facility is in accordance with current published Regulations under TSCA and has been inspected by EPA.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name John Bogen, Plant Manager
Street 4655 Biddle Avenue
City Wyandotte State MI Zip Code 48192
Signature John Bogen Date 6/8/81

☒ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other



4655 BIDDLE AVENUE, WYANDOTTE, MICHIGAN 48192 • (313) 285-9200

June 2, 1981

CERTIFIED MAIL

RETURN RECEIPT REQUESTED

U.S. EPA Region 5
Sites Notification
Chicago, Illinois 60604

Re: Notification of Hazardous Waste Sites
Pennwalt Corporation - Wyandotte Plant
EPA ID No. MID 005363114 (for existing, active hazardous
waste T/S/D facilities)

Gentlemen:

Enclosed please find three completed Notification of Hazardous Waste Site forms 8900-1 as required by Section 103(c) of the Comprehensive Environmental Response, Compensation and Liability Act of 1980 (PL 96-510).

Very truly yours,

PENNWALT CORPORATION


John Bogen
Plant Manager

JB:saj
Enclosure

JUN 12 1981



WYANDOTTE, MICHIGAN 48192

CERTIFIED MAIL

RETURN RECEIPT REQUESTED

CERTIFIED

PO# 2335079

MAIL

U. S. EPA REGION 5
SITES NOTIFICATION
CHICAGO, ILLINOIS 60604

